

**BRYANT ANNEX - KITCHEN EQUIPMENT FOR REPLACEMENT SCHEDULE**

Replacement Priority	ITEM#	QTY	DESCRIPTION	Make	Model	Serial Number	REMARKS	Life Expectancy	Date Equipment Put Into Service
1	1.03	1	WALK-IN COMPLEX (Freezer)	AMERICAN PANEL	FW3477.11TWL (Walk-In Unit) LAHA-032E-TAC-210 (Condensor #1) LET160BK (Evaporator for Condensor #1)	30725A D-1 (Walk-In Unit) ET 04C01859 (Condensor #1) D04A04512 (Evaporator for Condensor #1)	Replace Remote Condenser #1 located in the B1 level and Evaporator Located in the Walk-In	10	2005
1	1.03	1	WALK-IN COMPLEX (Refrigerator)	AMERICAN PANEL	FW2477.11TWL (Walk-In Unit) KAKA-0200-TAC-210 (Condensor #2) ADT 156AK (Evaporator for Condensor #2)	30725A D-2 (Walk-In Unit) ET 04B04710 (Condensor #2) T10G10530 (Evaporator for Condensor #2)	Replace Remote Condenser #2 located in the B1 level and Evaporator Located in the Walk-In	10	2005
1	3.06	1	WALK-IN REFRIGERATOR.	AMERICAN PANEL	FW3477.11TWL (Walk-In Unit) KAM1-0100-TAC-210 (Condensor #5) ADT 090AK (Evaporator for Condensor #5)	30725B (Walk-In Unit) ET 04C00428 (Condensor #5) T10F10365 (Evaporator for Condensor #5)	Replace Remote Condenser #5 located in the B1 level and Evaporator Located in the Walk-In	10	2005